1815 Sismet Road,
Mississauga,
Ontario, Canada
L4W 1P9
Tel: 905 602 5360
Fax: 905 602 7422

MARATHON INTERNATIONAL

October 11, 2011

RE: Luna 3 Comfort 1.310 Fi Indirect Tank Sensor Wiring

It has come to our attention the Luna 3 Comfort 1.310 Fi wiring for the indirect tank sensor has been wired incorrectly. As per the Luna 3 Comfort installation manual, pg. 28, the indirect tank sensor should connect up to the right side of the M2 bus terminal on connections 3 and 4. Please note that there should be two green wires coming from the control board connected to the left side of the M2 bus terminal on connections 3 and 4. In some instances, these two green wires may be attached to the left side of the M2 bus terminal on connections 5 and 6. If this is the case you will need to disconnect both green wires and reconnect them to terminals 3 and 4 on the left side of the M2 bus terminal. We apologize for any inconvenience this may have caused and thank you for your continued support in the Baxi product line.

Sincerely,

Jamie Jackson
Technical Director
Marathon International